

MID 142 - Mack

Mack

PID/SID	FMI	Fault Code	Fault Description
6	4, 3	4-6	Tachometer Output
7	4, 3	4-7	Speedometer Output
10	4, 3	4-3	Auxiliary Output #1
11	4, 3	4-4	Auxiliary Output #2
32	7, 8	3-8	Transmission Spitter Position
77	4, 3	2-5	Front Drive Axle Temperature Sensor
78	4, 3	2-6	Rear Drive Temperature Sensor
84	1	N/A	Road Speed
91	4, 3	5-1	Throttle Position Sensor
96	4, 3	6-1	Fuel Level
100	1	N/A	Oil Pressure Sensor
110	0	N/A	Engine Coolant Temperature
151	1, 0, 8	4-8	Customer Defined Statement
	7, 8	3-8	Transmission Spitter Position
167	1, 0	7-5	Alternator Voltage
168	1	7-5	Battery Voltage
173	0	N/A	Exhaust Temperature Sensor
	4, 3	3-1	Exhaust Temperature Sensor
177	0	N/A	Transmission Temperature Sensor
	4, 3	2-4	Transmission Temperature Sensor
190	0	N/A	Engine Speed Sensor
216	12	6-9	Other ECU Affecting Operations
231	8	6-4	J1939 Link
	14	6-8	J1939 Link
232	4, 3	5-2	Throttle Position Sensor Reference Voltage
235	3	7-2	Parking Brake Switch
236	2	6-7	Power Relay
237	3	1-6	Starter Input
238	4, 3	5-3	Engine Shutdown Lamp/Alarm
239	4, 3	5-5	Electronic Malfunction Lamp
242	3	7-4	Speed Control RESUME Switch

Mack (Continued)

PID/SID	FMI	Fault Code	Fault Description
243	3	7-3	Speed Control SET Switch
246	4	7-1	Service Brake Switch
250	8	6-3	J1708/J1587 Link
254	4	9-2	Power Reset Without Key Switch
	8	7-7	Exhaust Temperature Reference
	14	9-1	Transport Protocol

MID 158 - Mack

Mack

PID/SID	FMI	Fault Code	Fault Description
84	2, 4, 3, 5, 8, 11	4-1	Vehicle Speed sensor (VSS)